

No. 912-08

page1 of 4

Mandatory

Electronic module with at Filter ROTAX Engine Series 1912.

Exchange of both SMD electronic modules, part-no. 965 356. Subject:

Engines affected: All engines of series 912 A, from engine serial-no. 4,076.064 onwards

to engine serial-no. 4,380.753, installed in aircraft certified to JAR-VLA or equivalent requirements. In serial production the new type electronic module is installed beginning with engine serial-no. 4,380,754 onwards, and therefore no action is required from that engine serial no. and higher.

Electronic modules with integrated π -Filter protect the ignition unit from Reason:

> electromagnetic interference. Resulting from respective EMI-tests with modified electronic modules, the exchange of the electronic modules used up to engine serial no. 4,380.753 is considered necessary. All affected engines have to be retro-fitted therefore with the new modules

part no. 965 358.

Compliance: On all engines affected, this measure has to be taken at the next 100

hours check, but at the latest of 31th of december 1995.

Installation of the two electronic modules part-no. 965 358 according to Remedy:

the following instructions. These electronic modules are equal in size and

shape and therefore directly exchangeable.

Accomplishment: The necessary measures have to be taken and confirmed by the engine

producer or by persons entitled from the Aviation Authorities.

Approval: The statement of this Technical Bulletin has been approved by ACG at

2 4. AUG. 1995

Gunskirchen, 1995 08 16

BOMBARDIER-ROTAX GmbH

Dr. Heinz Lippitsch

di China

Ernst Möseneder



No. 912-08

page2 of 4

Instructions

Consult also Illustration 1, 2, 3 and 4 an page 3 and 4.

- 1) Disconnect minus terminal of aircraft battery.
- 2) Cut snap tie 1 of plug receptacle. Remove both Allen screws 2 M5x25 along with lock washer 3 and washer 1. Mark and unplug both 4-pole plug connections 5 of pick-up lines, the plug connection of the red charging lines 3 and the plug connection of the brown stop lines 7 Mark and unplug the plug connections of the yellow 3 and white line 9, of the threefold cable cord leading to the ignition coils. By removing hex. hd. screw 10 detach the grounding cables 11 (one each per electronic module). Both electronic modules can be taken off now.
- 3) Connect the new type of electronic modules part-no. ② . 965 358 in reversed sequence according to the marking or as shown on the wiring diagram (III. 4) and place the two electronic modules back to back on ignition coil bracket ③.
 - ◆ NOTE:

The two modules are identical and are marked on the front side with a serial and part number. The 4-pole plug for ignition circuit "A", marked blue and red on end of insulation hose shall be connected to the top module.

Attach electronic modules along with both cable assemblies, cable clamps and grounding cable with Allen screw M5x25. Attachment on the other side by Allen screw M5x25 and lock washer and washer .

■ ATTENTION: The metal braid over the two cable assemblies has to rest completely in the cable clamp .

For traction relief secure again both 4-pole plugs with snap tie ①. Attach all 5 grounding cables with the hex.hd. screw ② M6x16 and lock washer on intake manifold.

The complete ignition unit is company tested and furnished with a serial number 10.

- ◆ NOTE: This 4-digit number on top side of electronic module has to be fastened on the new type of electronic module.
- 4) Reconnect minus terminal of the aircraft battery.
- 5) Conduct ignition check.
- 6) New parts necessary


2x 965 358 electronic module 1x 866 710 cable strap

▲ WARNING: Failure to comply with this TB could result in engine damage and personal injury.




No. 912-08

page3 of 4



No. 912-08

page4 of 4



Lufttüchtigkeitsanweisung Nr.84 Geschäftszahl: 6454-1/61-95 AUSTRO CONTROL Flugmotor Kennzeichen: OE- ----**Flugtechnik** Rotax 912 A Serie Blatt ZI. 1 Blatt 1 Rotax 912 A-Serie Motore ab W.Nr. 4,076.064 bis einschließlich W.Nr. 4,380.752, 1. Betreff: welche in musterzugelassenen Luftfahrzeugen, ausgenommen Motorseglern, eingebaut sind. 2. Anlaß: Bei den im Betreff angeführten Motoren, deren Zündanlage mit SMD- Elektronikmodul TNr. 965356 ausgerüstet ist, können im Bereich starker Radiosender Zündstörungen auftreten, welche zu Leistungsverlust oder Motorstopp führen. 3. Maßnahmen: Diese sind aus der Technischen Mitteilung Nr. 912 - 08 der Firma Bombardier-Rotax vom 16. August 1995 zu entnehmen und werden Bestandteil dieser Lufttüchtigkeitsanweisung. 4. Fristen: Bei der nächsten 100 Stundenkontrolle, bzw. spätestens bis 31.Dezember 1995. 5.Durchführung: Die Maßnahmen sind von einem anerkannten Luftfahrttechnischen Betrieb oder von Personen mit entsprechender luftfahrtbehördlicher Berechtigung durchzuführen und im Bordbuch (Engine Logbuch) zu bescheinigen.

AIRWORTHINESS DIRECTIVE

No. 84

Affected Engines:

Rotax 912 A - Series engines S/N 4,076.064 up to S/N 4,380.752 incl .

Subject:

SMD-Electronicmodule P/N 965 356

Reason:

On subjected engines which ignition units are equipped with SMD-Electronic-module P/N 965 356 troubles could occure in aereas with heavy radio transmission leading to poor performance or stoppage of engine.

Action:

See Bombardier Rotax Technical Bulletin No. 912-08 issued August 16, 1995

which becomes herewith part of this AD.

Compliance:

At next 100 hour inspection, but not later then December 31, 1995.

Accomplishement and Logbook entry:

The required action has to be accomplished by an approved service station or by a licensed/qualified person and to be entered in the aircraft/engine log.