

SERVICE INSTRUCTION

MODIFIED CARBURETOR FLANGE FOR ROTAX ENGINE TYPE 912 (SERIES) AND ROTAX ENGINE TYPE 914 (SERIES)

SI-912-004

SI-914-006

Repeating symbols:

Please, pay attention to the following symbols throughout the Service Bulletin emphasizing particular information.

- ▲ **WARNING:** Identifies an instruction, which if not followed, may cause serious injury or even death.
- **ATTENTION:** Denotes an instruction which if not followed, may severely damage the engine or could lead to suspension of warranty.
- ◆ **NOTE:** Information useful for better handling.

1) Planning information

1.1) Engines affected

All versions of the engine type:

- 912UL up to S/N 4,403.539
- 912A up to S/N 4,417.990
- 912F up to S/N 4,412.798
- 912ULS up to S/N 4,425.518
- 912S up to S/N 4,922.520
- 914UL up to S/N 4,417.828 and 4,417.835
- 914F up to S/N 4,420.183 and 4,420.188 and 4,420.189

1.2) Concurrent ASB/SB/SI and SL

none

1.3) Reason

In the course of product refinement on the engines of the type 912 series and 914 series, a new carburetor flange of optimized shape has been introduced.

AUFGEHOBEN (ersetzt durch SB-912-030/914-019 (+UL) letzte gültige Ausgabe)
CANCELLED (superseded by SB-912-030/914-019 (+UL) latest edition)