



# SERVICE BULLETIN

## CHECKING OF OIL PUMP ATTACHMENT SCREW FOR ROTAX® ENGINE TYPE 912 UL (SERIES) SB-912-034UL

### **MANDATORY**

#### Repeating symbols:

- Please, pay attention to the following symbols throughout this document emphasizing particular information.
- ▲ **WARNING:** Identifies an instruction, which if not followed, may cause serious injury or even death.
  - **CAUTION:** Denotes an instruction which if not followed, may severely damage the engine or could lead to suspension of warranty.
  - ◆ **NOTE:** Information useful for better handling.

#### 1) Planning information

##### 1.1) Engines affected

All versions of the engine type:

- 912UL from S/N 3,792.501 to S/N 3,792.943 if Service Bulletin SB-912-032 has been carried out.
- Spare part supplies of oil pump assy. part no. 889590 that were supplied from October 31, 2001 until March 22, 2002 as spare parts.

For complete instructions and compliance to this service bulletin refer to Service Bulletin SB -912-034, latest edition section 1.2 onward.

- ◆ **NOTE:** Section 1.6) Approval: Is not required for engines of the type UL (series).  
Section 3) Accomplishment: In addition: persons with adequate type-specific training.

d01794