

SERVICE BULLETIN

INSTALLATION OF AN ELECTRIC STARTER WITH ENHANCED POWER FOR ROTAX_® ENGINE TYPE 912 AND 914 (SERIES) SB-912-037UL SB-914-023UL



Repeating symbols:

Please, pay attention to the following symbols throughout this document emphasizing particular information.

▲ WARNING: Identifies an instruction, which if not followed, may cause serious injury or even death.

■ CAUTION: Denotes an instruction which if not followed, may severely damage the engine or could lead to

suspension of warranty.

◆ NOTE: Information useful for better handling.

1) Planning information

1.1) Engines affected

All versions of the engine type:

912 UL from S/N 4,153.103
 912 ULS from S/N 4,425.001
 912 ULSFR from S/N 4,429.501
 914 UL from S/N 4,417.501

For complete instructions and compliance to this service bulletin refer to Service Bulletin- SB-912-037, SB-914-023, latest edition section 1.2 onward.

◆ NOTE: Section 1.6) Approval: Is not required for engines of the type UL (series).

Section 3) Accomplishment: In addition:persons with adequate type-specific training.