



SERVICE BULLETIN

CHECK OF ALLEN SCREW M8X100 IN THE CRANKCASE ON ROTAX® ENGINE TYPE 912/914 SB-912-047UL SB-914-032UL

MANDATORY

Repeating symbols:

Please, pay attention to the following symbols throughout this document emphasizing particular information.

- ▲ **WARNING:** Identifies an instruction, which if not followed, may cause serious injury or even death.
- **CAUTION:** Denotes an instruction which if not followed, may severely damage the engine or could lead to suspension of warranty.
- ◆ **NOTE:** Information useful for better handling.

1) Planning information

1.1) Engines affected

All versions of the engine type:

- 912 UL from S/N 4,407.247 to S/N 4,407.339
- 912 ULS from S/N 5,645.088 to S/N 5,645.350
- 912 ULSFR from S/N 4,430.141 to S/N 4,430.150
- 914 UL from S/N 4,419.052 to S/N 4,419.079

Following engines are already checked by the manufacturer and therefore not affected from this Service Bulletin:

- 912 UL: 4,407.267 / 4,407.279 to 4,407.289 / 4,407.296 to 4,407.326 / 4,407.329 to 4,407.335
- 912 ULS: 5,645.184 / 5,645.230 / 5,645.231 / 5,645.233 to 5,645.257 / 5,645.268 to 5,645.274 / 5,645.279 to 5,645.315 / 5,645.317 to 5,645.346
- 914 UL: 4,419.068 / 4,419.069

For complete instructions and compliance to this service bulletin refer to Service Bulletin SB-912-047/ SB-914-032, latest edition section 1.2 onward.

- ◆ **NOTE:** Section 1.6) Approval: Is not required for engines of the type UL (series).
Section 3) Accomplishment: In addition: persons with adequate type-specific training.