



SERVICE BULLETIN

REPLACEMENT OF PIN PART NO. 929700 IN CARBURETOR FOR ROTAX® ENGINE TYPE 912/914 (SERIES) SB-912-048UL SB-914-033UL

MANDATORY

Repeating symbols:

Please, pay attention to the following symbols throughout this document emphasizing particular information.

- ▲ **WARNING:** Identifies an instruction, which if not followed, may cause serious injury or even death.
- **CAUTION:** Denotes an instruction which if not followed, may severely damage the engine or could lead to suspension of warranty.
- ◆ **NOTE:** Information useful for better handling.

1) Planning information

1.1) Engines affected

All versions of the engine type:

- 912 UL from S/N 4,406.417 to S/N 4,407.377
- 912 ULS from S/N 5,643.752 to S/N 5,645.438
- 912 ULSFR from S/N 4,429.981 to S/N 4,430.213
- 914 UL from S/N 4,418.686 to S/N 4,419.132

Following engines are already checked by the manufacturer and therefore not affected from this Service Bulletin:

- 912 ULS 5,645.380 / 5,645.429 to 5,645.436
- 914 UL 4,419.103 to 4,419.107 / 4,419.119 / 4,419.126 / 4,419.127 / 4,419.128 / 4,419.130 / 4,419.134 / 4,419.135
- all CD-carburetors from S/N 04.2017 to S/N 05.3400, delivered as spare part until September 07, 2005.
- Also affected, are all engines equipped with pin part no. 929700 as a spare part in a CD-carburetor, installed from June 24 2004 to September 07 2005.

For complete instructions and compliance to this Service Bulletin refer to Service Bulletin -SB-912-048, SB-914-033, latest edition section 1.2 onward.

- ◆ **NOTE:** Section 1.6) Approval: Is not required for engines of the type UL (series).
Section 3) Accomplishment: In addition: persons with adequate type-specific training.

d03457