

SERVICE BULLETIN
CHECKING OR REPLACEMENT
OF FUEL PUMP PART NO. 892230/892235
FOR ROTAX® ENGINE TYPE 912 (SERIES)
SB-912-050UL

MANDATORY

Repeating symbols:

Please, pay attention to the following symbols throughout this document emphasizing particular information.

- ▲ **WARNING:** Identifies an instruction, which if not followed, may cause serious injury or even death.
- **CAUTION:** Denotes an instruction which if not followed, may severely damage the engine or could lead to suspension of warranty.
- ◆ **NOTE:** Information useful for better handling.

1) Planning information

1.1) Engines affected

All versions of the engine type:

- 912 UL from S/N 4,407.646 to S/N 4,407.847
- 912 ULS from S/N 5,646.084 to S/N 5,646.530
- 912 ULSFR from S/N 4,430.267 to S/N 4,430.307

Following engines are not affected:

- 912 ULS from S/N 5,646.517 to S/N 5,646.526

all parts

- Fuel pump, part no. 892230 and 892235, which was supplied as a spare part.

In addition are also effected, all engines and gearboxes installed with fuel pump part no. 892230 or 892235, has installed at engine repair/general overhaul.

- ◆ **NOTE:** All engines and gearboxes were already retrofitted with fuel pump part no. 892232 or 892236 are not affected.

For complete instructions and compliance to this service bulletin refer to Service Bulletin-SB-912-050, latest edition section 1.2 onward.

- ◆ **NOTE:** Section 1.6) Approval: Is not required for engines of the type UL (Series).
Section 3) Accomplishment: In addition: persons with adequate type-specific training.

AUFGEHOBEN (ersetzt durch ASB-912-053UL, letzte gültige Ausgabe)
CANCELLED (superseded by ASB-912-053UL, latest edition)